

## НОМЕНКЛАТУРА ПРЕОБРАЗОВАТЕЛЕЙ ТЕРМОСОПРОТИВЛЕНИЙ RTC.1088

Номер для заказа	Обозначение изделия	НСХ W <sub>100</sub>	Диапазон температур °С
02151500	RTC.1088.50M.50N50P	50M 1,428	-50...+50
02151101	RTC.1088.50M.50N100P	50M 1,428	-50...+100
02151151	RTC.1088.50M.50N150P	50M 1,428	-50...+150
02151181	RTC.1088.50M.50N180P	50M 1,428	-50...+180
02121500	RTC.1088.50M.20N50P	50M 1,428	-20...+50
02121101	RTC.1088.50M.20N100P	50M 1,428	-20...+100
02100500	RTC.1088.50M.0N50P	50M 1,428	0...+50
02100101	RTC.1088.50M.0N100P	50M 1,428	0...+100
02100121	RTC.1088.50M.0N125P	50M 1,428	0...+125
02100151	RTC.1088.50M.0N150P	50M 1,428	0...+150
02100181	RTC.1088.50M.0N180P	50M 1,428	0...+180
02251500	RTC.1088.100M.50N50P	100M 1,428	-50...+50
02251101	RTC.1088.100M.50N100P	100M 1,428	-50...+100
02251151	RTC.1088.100M.50N150P	100M 1,428	-50...+150
02251181	RTC.1088.100M.50N180P	100M 1,428	-50...+180
02221500	RTC.1088.100M.20N50P	100M 1,428	-20...+50
02221101	RTC.1088.100M.20N100P	100M 1,428	-20...+100
02200500	RTC.1088.100M.0N50P	100M 1,428	0...+50
02200101	RTC.1088.100M.0N100P	100M 1,428	0...+100
02200121	RTC.1088.100M.0N125P	100M 1,428	0...+125
02200151	RTC.1088.100M.0N150P	100M 1,428	0...+150
02200181	RTC.1088.100M.0N180P	100M 1,428	0...+180
02522500	RTC.1088.Pt100.200N50P	Pt100 1,385	-200...+50
02511101	RTC.1088.Pt100.100N100P	Pt100 1,385	-100...+100
02551500	RTC.1088.Pt100.50N50P	Pt100 1,385	-50...+50
02551101	RTC.1088.Pt100.50N100P	Pt100 1,385	-50...+100
02551151	RTC.1088.Pt100.50N150P	Pt100 1,385	-50...+150
02551181	RTC.1088.Pt100.50N180P	Pt100 1,385	-50...+180
02551201	RTC.1088.Pt100.50N200P	Pt100 1,385	-50...+200
02551351	RTC.1088.Pt100.50N350P	Pt100 1,385	-50...+350
02521500	RTC.1088.Pt100.20N50P	Pt100 1,385	-20...+50
02521101	RTC.1088.Pt100.20N100P	Pt100 1,385	-20...+100
02521201	RTC.1088.Pt100.20N200P	Pt100 1,385	-20...+200
02500500	RTC.1088.Pt100.0N50P	Pt100 1,385	0...+50
02500101	RTC.1088.Pt100.0N100P	Pt100 1,385	0...+100
02500121	RTC.1088.Pt100.0N125P	Pt100 1,385	0...+125
02500151	RTC.1088.Pt100.0N150P	Pt100 1,385	0...+150
02500181	RTC.1088.Pt100.0N180P	Pt100 1,385	0...+180
02500201	RTC.1088.Pt100.0N200P	Pt100 1,385	0...+200
02500251	RTC.1088.Pt100.0N250P	Pt100 1,385	0...+250
02500301	RTC.1088.Pt100.0N300P	Pt100 1,385	0...+300
02500351	RTC.1088.Pt100.0N350P	Pt100 1,385	0...+350
02500401	RTC.1088.Pt100.0N400P	Pt100 1,385	0...+400
02500501	RTC.1088.Pt100.0N500P	Pt100 1,385	0...+500
02500601	RTC.1088.Pt100.0N600P	Pt100 1,385	0...+600
02422500	RTC.1088.100П.200N50P	100П 1,391	-200...+50
02411101	RTC.1088.100П.100N100P	100П 1,391	-100...+100
02451500	RTC.1088.100П.50N50P	100П 1,391	-50...+50
02451101	RTC.1088.100П.50N100P	100П 1,391	-50...+100
02451151	RTC.1088.100П.50N150P	100П 1,391	-50...+150
02451181	RTC.1088.100П.50N180P	100П 1,391	-50...+180
02451201	RTC.1088.100П.50N200P	100П 1,391	-50...+200
02451351	RTC.1088.100П.50N350P	100П 1,391	-50...+350
02421500	RTC.1088.100П.20N50P	100П 1,391	-20...+50
02421101	RTC.1088.100П.20N100P	100П 1,391	-20...+100
02421201	RTC.1088.100П.20N200P	100П 1,391	-20...+200

Номер для заказа	Обозначение изделия	НСХ W <sub>100</sub>	Диапазон температур °С
02400500	RTC.1088.100П.0N50P	100П 1,391	0...+50
02400101	RTC.1088.100П.0N100P	100П 1,391	0...+100
02400121	RTC.1088.100П.0N125P	100П 1,391	0...+125
02400151	RTC.1088.100П.0N150P	100П 1,391	0...+150
02400181	RTC.1088.100П.0N180P	100П 1,391	0...+180
02400201	RTC.1088.100П.0N200P	100П 1,391	0...+200
02400251	RTC.1088.100П.0N250P	100П 1,391	0...+250
02400301	RTC.1088.100П.0N300P	100П 1,391	0...+300
02400351	RTC.1088.100П.0N350P	100П 1,391	0...+350
02400401	RTC.1088.100П.0N400P	100П 1,391	0...+400
02400501	RTC.1088.100П.0N500P	100П 1,391	0...+500
02400601	RTC.1088.100П.0N600P	100П 1,391	0...+600
02322500	RTC.1088.50П.200N50P	50П 1,391	-200...+50
02311101	RTC.1088.50П.100N100P	50П 1,391	-100...+100
02351500	RTC.1088.50П.50N50P	50П 1,391	-50...+50
02351101	RTC.1088.50П.50N100P	50П 1,391	-50...+100
02351151	RTC.1088.50П.50N150P	50П 1,391	-50...+150
02351181	RTC.1088.50П.50N180P	50П 1,391	-50...+180
02351201	RTC.1088.50П.50N200P	50П 1,391	-50...+200
02351351	RTC.1088.50П.50N350P	50П 1,391	-50...+350
02321500	RTC.1088.50П.20N50P	50П 1,391	-20...+50
02321101	RTC.1088.50П.20N100P	50П 1,391	-20...+100
02321201	RTC.1088.50П.20N200P	50П 1,391	-20...+200
02300500	RTC.1088.50П.0N50P	50П 1,391	0...+50
02300101	RTC.1088.50П.0N100P	50П 1,391	0...+100
02300121	RTC.1088.50П.0N125P	50П 1,391	0...+125
02300151	RTC.1088.50П.0N150P	50П 1,391	0...+150
02300181	RTC.1088.50П.0N180P	50П 1,391	0...+180
02300201	RTC.1088.50П.0N200P	50П 1,391	0...+200
02300251	RTC.1088.50П.0N250P	50П 1,391	0...+250
02300301	RTC.1088.50П.0N300P	50П 1,391	0...+300
02300351	RTC.1088.50П.0N350P	50П 1,391	0...+350
02300401	RTC.1088.50П.0N400P	50П 1,391	0...+400
02300501	RTC.1088.50П.0N500P	50П 1,391	0...+500
02300601	RTC.1088.50П.0N600P	50П 1,391	0...+600